



NOTICE TO MARINERS 11/2017

Date of issue 15th November 2017

Dunoon Ferry Terminal Berth (Breakwater) Approaches

Following a recent Bathymetric survey a build up of silt (ridge) approx.. 30M SE of the Southern end of The Victorian Pier was discovered (Position 55°56'45.4N 4°55'16.6W)

Vessels are asked to approach ferry berth from the east at Low water to avoid silt build up .

A dredging programme will shortly be in place.

A further NTM will be issued in due course to provide updated information

Contact Dunoon Pier on channel 12

Tel 01369702652

e-mail [paul.lambert@argyll-bute .gov.uk](mailto:paul.lambert@argyll-bute.gov.uk)

Paul Lambert Harbourmaster Dunoon

