

## **NOTICE TO MARINERS 01/2016**

**Date of issue 31<sup>st</sup> August 2016**

### **Dunoon Ferry Terminal Berth (Breakwater) Approaches**

**Following a recent Bathymetric survey a build up of silt (ridge) approx.. 30M SE of the Southern end of The Vitorian Pier was discovered (Position 55° 56' 45.4N 4° 55' 16.6W)**

**Vessels are asked to approach ferry berth from the east at Low water to avoid silt build up .**

**A dredging programme will shortly be in place.**

**A further NTM will be issued in due course to provide updated information**

**Paul Lambert Harbourmaster Dunoon**