



Rothesay Harbour

Notice to Mariners 03 /19

Unlit Port Hand Lateral Buoy

Mariners are advised that the Port hand Lateral mark (fl. Red 5s) at the entrance to Rothesay Harbour is currently unlit.

Steven Neilson

Harbour Master

Rothesay Harbour

(t) 01700 503842

12th November 2019