

**Notice to mariners 04/2016**

**Date of issue 21<sup>st</sup> April 2016**

**Dunoon Ferry terminal- Ferry Terminal berth (Breakwater)Approaches**

Due to a reduction in available depth of water at low water at position 55°56'45.4N 4°55'16.6W approx. 30M SE of Southern end of Victorian pier vessels are asked to approach the ferry berth from the east to avoid silt build up around Victorian pier.

A periodic bathymetric survey is scheduled to commence shortly.

A further Notice to mariners will be issued in due course to provide updated information.

**Paul Lambert**

**Harbourmaster Dunoon**



Harbour Master's Office  
Dunoon Pier, Dunoon, Argyll. PA23 7HU  
Telephone: 01369 702652 Fax: 01369 708623 E-mail: paul.lambert@argyll-bute.gov.uk